

# Rouge River AOC Colonial and Venoy Restoration Photo Summary through September 2022

## VENOY

May 12, 2022  
Invasives removal



May 20, 2022  
Silt fence



May 13, 2022  
Silt fence



July 28, 2022  
Topsoil stripping



May 19, 2022  
Silt fence



August 4, 2022  
Topsoil removed





# Rouge River AOC Colonial and Venoy Restoration Photo Summary through September 2022

August 9, 2022  
Excavating wetland by the road



August 16, 2022  
Grading wetland



August 10, 2022  
Trash and log piles



August 18, 2022  
Grading



August 12, 2022  
Grading wetland



August 26, 2022  
Wetlands staked out





# Rouge River AOC Colonial and Venoy Restoration Photo Summary through September 2022

August 30, 2022  
Excavating by the creek



September 9, 2022  
West wetland stabilization



September 1, 2022  
Invasives area




September 13, 2022  
Culverts by east wetlands



September 6, 2022  
Streambank Stabilization



September 16, 2022  
Wayne County parking lot excavation



# Rouge River AOC Colonial and Venoy Restoration Photo Summary through September 2022

September 20, 2022  
East wetland graded



September 28, 2022  
Wetland edge logs

